Project

Bond projects Athletics - Track Materials and Labor for Portable Fire Extinguisers Hazardous Waste Disposal Recarpet Rooms 83, 85, Portable rooms 312, 815 and Wellness Center Bonus Room 1 Recarpet Band Room and Closets Roofing project for FHS Principal's Office, Palomar Bldg., Staff Restrooms, Girls Locker Room, Old and New Gyms Recarpet Band Room and Closets Legal Fees for Construction Issues Plans for Library, Cafeteria, Amphitheater Facilities Consultant Restroom modernization five restrooms Fiberoptic cable

Architectural Services

Replace restroom doors Local Governments initial fee

Cable Installation Restroom modernization five restrooms

Restroom modernization five restrooms Repair trip hazards in concrete Restroom modernization five restrooms Security Cameras Provide topographic and Utility surveying GO Bond financial and performance audit Provide and Replace AC Unit Provide and Replace AC Unit

Provide and Replace 2 VTAC Units

Provide and Replace 2 VTAC Units Hazardous Waste Removal Recarpet Rooms 80 & 81 Recarpet Rooms 11, 21, 23, 84 Recarpet Ivy Rooms 3, 6, 7, 8 Quality Bidders Annual Software Spt Fee Consulting and Inspection Services Legal Fees Facilities Consultant

Telephone Services Architectural Services Post Construction Evaluation

Description

Provide topographic and boundary surveying Hy-Tek Meet Manager Timing System Materials and Labor for Portable Fire Extinguisers Hazardous Waste Disposal Recarpet Rooms 83, 85, Portable rooms 312, 815 and Wellness Center Bonus Room 1 Remove and Recarpet Band Room and Closets

General Contractor Remove and Recarpet Band Room and Closets Legal Fees for Construction Issues Project Fees

General Contractor Replaced broken cable for PAC Restroom & Library refresh, Modernization, and Master Planning

Purchase of new doors on media center restrooms Financial Services related to bond Installation of fiberoptic cable in PAC and outside main school access gates Environmental consulting services Settlement of contract for work completed, items delivered Repair trip hazards in concrete DSA Class III Inspector Security Cameras Provide topographic and Utility surveying GO Bond financial and performance audit Provide and Replace AC Unit in Room 80 Provide and Replace AC Unit in room 22 Provide and Replace 2 VTAC wall mounted systems in Classroom 73 Provide and Replace 2 VTAC wall mounted systems in **Counseling Office** Hazardous Waste Removal Remove and Recarpet Rooms 80 & 81 Remove and Recarpet Rooms 11, 21, 23, 84 Recarpet Ivy Rooms 3, 6, 7, 8 Quality Bidders Annual Software Support Fee Project Inspection Service Legal Fees related to Bond issues

Mitel Support, Activate SLA, Mobile Device License with Push Notifications, Revolution Notivication Platform License Modernization construction doc's, DSA Approval Post Construction Evaluation

Fire Alarm Replacement

Install Smoke Seals in PAC

Door Locksets Replaced Door Locksets Replaced Door Locksets Replaced Door Locksets Replaced Door Locksets Replaced

Door Locksets Replaced

Window Films

Window Films Asphalt Repairs Upper Ivy Total East Fencing FHS Perimeter Fence

Emergency Repair of Collapsed Pipe in Ag Driveway Security Cameras Security Cameras Security Cameras Security Cameras HVAC Unit 40-Ton Heavy Lift Crane Outside Leak Detection on Fire System Quality Bidders Annual Software Spt Fee Construction Testing & Engineering Consulting and Inspection Services

Competition Courts Repair Project Fees Facilities Consultant 40ton AC Unit AC/Heating Unit AC/Heating Unit

AC/Heating Unit

Telephone Services Architectural Services Post Construction Evaluation Fire Alarm Replacement LED Light Bulbs, Flat Panels

Replace Roof Top Mounted HVAC

Fire Alarm Replacement Insall Smoke Seals across the backside of the prosemium arch in the PAC Principal's Office, District Office, Portable #1 Door Lockset Replaced Theater Doors Lockset Replaced Boys & Girls Restrooms 55A, 55B, 52A, 52B Counseling Ext/Int, Principle 15

Stadium Restrooms Option One with new door frames Window Film applied to District Office, Cafeteria, Cooks Kitchen and Athletic Office Window Film applied to Counseling Offices and Principal's Office Asphalt repairs to 6 different areas on campus Install 500 LF of 8" Chain Link Fence FHS Perimeter Fence

Emergency Repair of Collapsed Pipe in Ag Driveway 17 Outdoor Cameras & Licenses 275 Creative Cloud Subscriptions 37 Surveillance Cameras 17 Surveillance Cameras HVAC Unit for Room 85 109' Boom for Kitchen HVAC install Outside Leak Detection on Fire System Quality Bidders Annual Software Support Fee FHS Modernization Project Inspection Service Clean and repair all surfaces, remove and replace all posts, repaint, replace nets and install new windscreen associated with competition courts. Project Fees

40ton AC Unit for PAC AC/Heating Unit for JROTC AC/Heating Unit for Classroom 72 AC/Heating Unit Replacements District Office Business Services Mitel Support, Activate SLA, Mobile Device License with Push Notifications, Revolution Notivication Platform License Modernization construction doc's, DSA Approval Post Construction Evaluation Fire Alarm Replacement Parking Lot Lighting Replace one roof top mounted HVAC unit with a new carrier unit in the Library, located in the media center 200's building.

Door Locksets Replaced PAC Lighting

DSA Project Inspector Services FHS Perimeter Fence

STEAM Lab Classroom, Modernization 5ton AC Unit 5ton AC Unit

BACnet Communicating Thermostats

Telephone Services

Air Conditioning & Heating Air Conditioning & Heating

Asbestos & lead Inspection Refrigeration upgrades

Infrastructure modernization/utility improvements Legal Fees for Construction Issues PAC modernization Utility improvements

Infrastructure modernization

Quality Bidders Annual Software Spt Fee

Facilities Consultant

Technology Infrastructure modernization Technology Infrastructure modernization Infrastructure modernization Infrastructure modernization Upgrades/furniture Utility improvements Technology Infrastructure modernization Upgrades/furniture Upgrades/furniture AC/Heating Unit AC/Heating Unit Infrastructure modernization

DR#131, West Gym Pair, Boys AG, Girls AG PAC Lighting DSA Project Inspector Services for the Fallbrook High School Whole Site Modernization Phase 1 and Closeout DSA #04-118359 **FHS** Perimeter Fence STEAM Lab Classroom Addition and modernization of selected edcation buildings on FHS Campus Rooftop AC Unit 5ton AC Unit 150 BACnet Communicating Thermostats to be installed by FUHSD HVAC personnel. Replace Bard heat pump for the Welcome Center room 117. Purchase and transport new system to the facility and remove and dispose of old system. Install the new system in same location. Rebuild Primary Condenser Water Pump & Motor including Pump Machining Replaced two boilers. Asbestos haardous Emergency Response Act (AHERA) 3 Year Re-inspection. Prepared Lead Paint and Universal Waste Removal Specification.

Gate valves with weld flanges, ball valve test ports down stream of new gate valves, cement line interior of weld joints and exterior of existing pipes. Paint safety red. Legal fees related to Bond issues FHS PAC hazer, fans, tranceiver, receiver, cables

Demo existing sheet vinyl and dispose of, install Armstrong Medintone sheet vinyl flooring. Resurfaced for correct bond.

To provide CUPCCAA registration review services for the 2021-22 school year

District facility support services for 2021-22 school year

Charges to move Shortel lines during FHS Modernization Cabling for FHS classroom modernization

AG 500 exterior door, install HMD FHS cafeteria tables

Cabling for FHS classroom modernization FHS library shelving units FHS library full top desk FHS rm 320 bard replacement HVAC system HVAC system building 500 - AG bid #2021-06 Installation of room 500 door

Upgrades/furniture Technology Infrastructure modernization

Infrastructure modernization

Security Film for Library/Cafeteria windows AC/Heating Unit

Lighting efficiency upgrades

Asbestos abatement

Technology Infrastructure modernization

Infrastructure modernization/utility improvements Technology Infrastructure modernization

Classroom upgrades: carpet

Topographic field survey

Infrastructure modernization/utility improvements

Architectural Services

Architectural Services

Infrastructure modernization/deferred maitenance

Infrastructure modernization Sinks in library

STEAM Lab Classroom, Modernization

DSA Project Inspector Services DSA Project Inspector Services Pit cover for FHS PAC Outdoor cafeteria tables for FHS Emergency notification solution for FHS Remove and install doors and hardware. Snackbar, custodial room, girls and boys gym, staff visitors

Apply safety/security film to cafeteria and library windows. Glass shield for graffiti and cratch prevention. Motor drive for 40 ton HVAC unit lower 200's Install 72 light fixtures in 5 classrooms in the 50's building. Instarll wireless Vive system with motion sensors and wireless remote for control of lighting.

Asbestos abatement of 12 2x2 spots for fire alarm FHS Sensors for restrooms; furnishing and installation, camera at MAC

To provide civil engineering services for the FHS CTE Project to include grading, drainage, site utilities for sewer, domestic water and horizontal control plans. To provide field topographic survey. Cabling for FHS classroom modernization

FHS Lunchroom 4000 sq. ft carpet, clean existing concrete by mechanical auto scrubber and recoat with 2-3 coats acrylic sealer to produce clean polished substrate. Fill damaged concrete prior to coating. To provide field topographic survey for the FHS CTE Project.

Excavate and install 3 concrete catch basins with cast iron grate. Excavate and install filltings to storm drain.

Project for FHS Baseball Field Bleachers Replacement Architectural Services, Design, Document, Bidding, Administration, Structural Engineering,

Labor and materials to re-roof the FHS goat barn. Replace dmaged roof underlay, install poly glass torch down to seal where metal roof meet pitched roof. Install new drip edge #30 felt and 30-year timberline GAF shingles. Copper roof drain, sawcut concrete, chased pipe. CCTV new strom drain. Sawcute and excavate from pipe dead end to new storm drain, saddle connect and install. Tested, replaced concrete. Install sink counter areas FHS library Project review fees for the FHS new STEAM Lab and Modernization FHS Modernization Project Plan Review: for access, fire & life safety and structural reviews Request for re-examination FHS Project Pit cover for FHS PAC

DSA Project Inspector Services

Architectural Services Architectural Services AC/Heating Unit Plan/Field review of Application for FHS To provide services for the Aquatics Center Replacement Project FHS HVAC Replacement Project Remove existing and supply new fan FHS